US ERA ARCHIVE DOCUMENT

UNIT LOG		1. Incident Name 2		2. Date Prepared	3. Time Prepared
		Kalamazoo River/Enbridge Oil Spill		06/06/2012	1600
		5. Unit Leader	5. Unit Leader (Name and Position)		6. Operational Period
		Melinda Luetke, Planning Section Chief			0700, 05/31/12 –
				0700, 06/07/12	
7.		l	Personnel Ros	ster Assigned	1
	Name		ICS Position		Home Base
	Matthew Haak		Situation Unit Leade	r	Chicago, Illinois
8.			Activity Log		
Time	Major Events				
09:00	9:00 Operational status:				
	 C0.4 Boat Launch, observed sweep boat crew preparing to go down to the dam. Sheen observed at C0.4 boat launch. Tar glob and sheen observed along the Ceresco Dam boom. Sheen observed along the Ceresco Dam boom. Ceresco Dam, crew observed performing boom maintenance. MP5.63 LDB near peninsula, sheen observed. MP5.55 LDB, sheen observed. MP27.75 LDB, sheen observed. MP30.0 LDB, poling crew observed. MP30.25 RDB, poling crew observed. MP30.8, Containment branch crew observed. MP37.75, Poling crew observed. Sheen sweep boat observed operating along the E4 boom. MP37.75, Sheen observed upstream of the E4 boom. MP37.0 Island located in the eastern portion of the Delta, sheen observed. Large Island located in southeast corner of the Delta sheen observed. Sheen observed in southeast corner of the Delta. MP30.75, Poling crew observed. MP29.5, Poling crew observed. MP29.5, Poling crew observed. MP29.25, absorbent boom placed in downstream portion of channel. MP29.25, back channel sheen observed in areas stepped in. MP22.25, Poling crew observed. MP21.5, sheen observed within river channel. MP21.5, sheen observed within river channel. MP22.75, Poling crew observed. Additional observations: None				
15:00	Return to ICP.				
). Prepare	ed by (Name an	d Position)		

Matthew Haak, Situation Unit Leader, USEPA-START